

NZ POISONS CENTRE 0800 764 766 | NZ EMERGENCY SERVICES: 111 - THIS IS A SUMMARY ONLY - FULL REPORT AVAILABLE
CRC (NZ) 3063 CDT Cutting Oil (Aerosol)

INGREDIENTS	CAS NO	%	TWA
LPG (liquefied petroleum gas)	68476-85-7.	10-30	1800 mg/m3
mineral oil	Not Available	>60	5 mg/m3

GHS	DG
	
	UN No: 1950 Hazchem Code: Not Applicable DG Class: 2.1 Subsidiary Risk: Not Applicable Packing Group: Not Applicable

HEALTH HAZARD INFORMATION

Determined by Chemwatch using GHS/HSNO criteria	2.1.2A, 6.3B
Signal word:	Danger
Hazard statement(s):	H222 Extremely flammable aerosol. H316 Causes mild skin irritation.

PRECAUTIONS FOR USE


Glasses:	Consider chemical goggles.
Gloves:	When handling larger quantities:
Respirator:	Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation:	Store in cool, dry, protected area. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. Keep out of reach of children. Keep container in a well ventilated place. Keep away from heat. Keep away from sources of ignition. No smoking.
Fire/Explosion Hazard:	HIGHLY FLAMMABLE. Vapours/gas heavier than air. Toxic smoke/fumes in a fire. Risk of explosion if heated under confinement. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. In case of fire and/or explosion, DO NOT BREATHE FUMES.

PROPERTIES


Liquid. Gas. Does not mix with water. Floats on water. Extremely flammable.

EMERGENCY

FIRST AID

Skin:	Wash with soap & water. Apply cleansing cream.
Advice To Doctor:	Emesis generally unnecessary. Debride for subcutaneous injection.
Fire Fighting:	Keep containers cool. Foam.
Spills and Disposal:	Eliminate ignition sources. Absorb with dry agent. Stop leak if safe to do so. Use only in well ventilated areas. Take precautionary measures against static discharges. Dispose of this material and its container at hazardous or special waste collection point. This material and its container must be disposed of in a safe way.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS


X — Must not be stored together

0 — May be stored together with specific preventions

+ — May be stored together